



Kent County
Road Commission


2015 Bridge Conference

Bay City Michigan

March 18, 2015

Pine Island Drive Bridge Restoration

LTU Beam Testing Update



Location







Original truss bridge being removed in 1925



Typical 1920's truss bridge

Steel vs Concrete Life Cycle Costing

- Concrete
- First cost \$31653
- No annual maintenance
- Depreciation \$7913
- Cost in Perpetuity \$39,567
- Steel
- First Cost \$28,276
- Est annual maint 110
- Depreciation \$16,888
- Cost in Perpetuity \$45,165

Bridge 410202

Comparative estimates of cost with reinforced concrete girder superstructure and with steel truss superstructure, both 100' span, 20' roadway.

Actual payments on contracts for concrete abutments and concrete superstructure:-

Abutments.	Jump Sum	\$5674.11
241 Cu. Yds. Grade C Concrete		
Piling.	2296 Lin. Ft. @ \$1.00	2296.00
Superstructure.		19105.00
370.3 Cu. Yds. Grade A	@ \$30.00 =	\$11109.00
39350 lbs. Reinf. Steel	@ .08 =	3148.00
30300 Structural Steel	@ .16 =	4848.00
Cement Furnished Abutments		865.18
Superstructure		1622.79
Engineering and Supervision		<u>2090.72</u>
Total Estimate of First Cost	-----	31653.80
Annual Maintenance		
Annual Depreciation Assume		
= 1% x \$31,650.00	=	\$316.50
Capitalized @ 4%	=	<u>-7913.50</u>
Estimated Total Cost in Perpetuity	-----	\$39567.30

Estimated cost for steel superstructure and concrete abutments:-

Abutments	-----	\$5746.80
Piling	-----	2296.00
Steel Superstructure	168,000 lbs. @ \$.085 =	14280.00
Concrete Floor	43.5 Cu. Yds. @ \$45.00 =	1957.50
	11650 lbs. Reinf. Steel @ .07 =	815.50
Cement	Abutments	865.18
	Floor	191.00
Engineering and Supervision		2310.00
Field Painting		<u>325.00</u>
Total Estimate of First Cost	-----	\$28276.98
Annual Maintenance	\$110.00	
Annual Depreciation Assume		
= 2% x \$28,277.00	=	565.54
Estimated Annual Depreciation and Maintenance	=	675.54
Capitalized @ 4%	=	<u>-16888.50</u>
Estimated Total Cost in Perpetuity	-----	\$45165.48

Bid Documents

- Notice to Contractors 1 page
- Notice to Bidders 3 pages
- Special Provisions and Bid Sheet 1 page
- Plan sheets - 2

SPECIFICATIONS

State Reward Bridge No. 410202

The specifications to be followed in performing this work shall be the Department's "General Specifications" for bridges, Fifth Edition 1922, supplemented by the "Additions and Changes" Effective September 20th, 1922, the attached "Instructions to Bidders" of April 3rd, 1923, and such special provisions as are contained herein.

STATE CEMENT: Cement will be furnished by the State f.o.b. Englishville.

SPECIAL SPECIFICATIONS

Falsework Piling must be of 10 ton capacity with 12 inch butts, 6 inch tips with alignment joining centers of butts and tips falling inside the pile throughout. Piles need not be peeled.

Bents are not to be spaced over 10 feet center to center. 3 Piles per bent centered under each girder, with 2 intermediate piles per bent, also outrigger piles from outside bracing to be placed 9 feet from center of girder with a total of 10 piles per bent are required. All floor lagging is to be 2 inch T & G, no tar paper being permissible.

Girder joist shall consist of 12 2x12 yellow pine per girder or equivalent. Complete longitudinal bracing consisting of 2 planes of 3x8 wales and cross braces will be required in alternate panels, extending to low water level and similar bracing of one plane type will be required at each bent. 6"x6"x2'0" oak wedges will be required at each bent for complete control of camber. Concrete buggies are to be supported in such a manner that deflection of supports and vibration will not affect the work being cast.

Sponting will not be permitted.

All exposed surfaces except bottom of floor inside of girders is to be given a carborundum rub.

All excavated material handled in connection with this job is to be disposed of as directed by the Engineer.

No concrete is to be cast in freezing weather

The bridge floor is to be cured by the ponding method, damming both ends of the bridge and sealing all drain openings and keeping the floor flooded with not less than 1½" depth of water at all times during a two week's period after the pouring of any section of the floor.

The superstructure is not to be merely moistened, but is to be kept damp, using burlap or straw coverings and keeping the forms wet constantly for a period of not less than two weeks after pouring any unit.

ITEMIZED BID

<u>Approx. Quantity</u>	<u>Item of Work</u>	
(1) 360.3	Cu.Yds	Grade A concrete -----
(2) 39350	Lbs.	Bar Steel Reinforcement -----
(3) 30300	"	Structural Steel Reinforcement -----


Notice

Falsework sketches must be submitted with the proposal in order to entitle it to consideration as time is an essential element on this job. It is specifically understood that the items and prices as given above constitute full and complete basis for compensation for all work required in connection with this Proposal.

Br. 410202



Note the falsework





The “batch plant” on the deck with a barrel of state supplied cement



Typical “improved” road of the 1920’s




Road Commission WW 1 surplus trucks



This is our first new truck, purchased to replace old worn-out war equipment.

Road Commission's first truck purchased new -1924 United- built in GR




Concrete paving train – material delivery by narrow gauge RR



Gasoline engine powered excavator

State of the art
Detour signing






Asphalt paving – where's the paver?



It's an "Armstrong paver" – asphalt mixed on site in a concrete style batch mixer



Have to have those pavement markings (and a cigarette 😊)



Road Commissioners inspecting the “New” concrete pavement surface grinder

Bridge Replacement Program

- 1968-1977 local bridge program

- 3-party agreement

25% township \$35,000 / year

25% County of Kent \$35,000 / year

50% KCRC \$70,000 / year

Bridges by contract

Culverts by county forces (“the bridge crew”)

- 2nd 10 year program 1979-1988
 - 64 bridges / culverts
 - 25% County of Kent \$61,000 / year
 - 10% Townships \$18,000 / year
 - 65% KCRC \$167,000 / year

Very successful in getting bridge and culvert needs addressed

Manager ended the bridge crew

1983 Replacement

- Functionally obsolete – only 20 feet wide
- Structurally sound, minor deterioration
- Low traffic count – 700ADT
- \$300,000 to remove and replace
- \$215,000 to build a second bridge

Recommendation - leave until the 2nd is needed.



2006

Western Michigan Branch
American Society of Civil Engineers
nominated the bridge as an
ASCE State Historic Site

Algoma Township Historical Society
pursued State Historic Site Status

2014 Enhancement Grant

\$193,500 for restoration / rehabilitation

Contract amount \$261,791

Contractor L.W. Lamb

**This Old
House**

is a lot like

**This Old
Bridge**

Recent Photos - 2009



Despite the bridge's age – it still is a graceful structure

Modest Spalling, Graffiti, Mold, and Failed Past Repair Efforts All Contributed to Make the Bridge a Bit of an Eyesore



But For 90 Years Old – It could be
Worse



And In Some Places It Was Worse....



Amazing What You Can Do in 24 Hours



First Step – Milling. This is a lot like Christmas Morning – You Never Know What You'll Get....



In June 2014 We Cleaned Some Test Areas
So We Could Match the Color (hopefully)



In Hindsight, We Should Have
Initiated the Test Cleaning Process
in June 2013, Not 2014....

My stomach went into a knot when I saw this...



This was easier to stomach



Only minor chipping was required on the inside faces of the “truss”



Vertical Reinforcement in “pilaster”



After Hand Chipping – Our Next Step Was to “Soda Blast” the Interior of the Truss

- ° Soda Blasting is Similar to “Sand Blasting”, except Baking Soda is Used as the Medium
- ° Baking Soda is “Soft” and Not Really Abrasive
- ° Baking Soda also provides some moderate cleaning properties, much like consumer products with Baking Soda...

“Inside” Of The Bridge After Soda Blasting



After Soda-Blasting (7/25/14)



East Side of Exterior – After Power Washing



All areas have been soda blasted, the lower area had also been sand blasted. The lower area used to have epoxy over it



Former Epoxy Covered Area – all concrete substrate was not “perfect” – some surfaces still harbor a little epoxy



S-2 Trial Mix for Balustrade – 5 Days After Placement



CL Mixes at 5 days – we are very concerned.....(too brown)



Overall – color results were good with a few “initial outliers”



More Patchwork.....

TEXTURE WILL BE
ENHANCED BY APPLICATION
OF "SAND-CEMENT"
TEXTURE


SMALL VOID –(THIS WAS
FILLED). SPRUE WAS REMOVED
TOO



Same Patch Area, 3 Weeks Before



Finished Results....



Interior, East Side, Before



Interior, East Side, After



West Fascia - After



East Fascia - Before



East Fascia - After



Lessons Learned:

- * For this situation, it seems power washing is almost as good as soda blasting
- * If your bridge has an HMA overlay, it probably has some “issues” on the underlying deck
- * Color match and attention to detail when using latex-modified patching mix are critical
- * Surface Treatment/Texturing should be mentioned in any specification



HISTORIC SITE

PINE ISLAND DRIVE BRIDGE

The Pine Island Drive Bridge is a rare Michigan example of a reinforced concrete rainbow arch bridge. A type of through arch design, this bridge, built between 1922 and 1924, replaced a steel truss bridge. The low river banks at the crossing of the Rogue River required the supporting trusses to be raised above the bed of the one-hundred-foot stream, giving the bridge its unusual form. Designed by Michigan State Highway Department bridge engineer Charles J. Allick, PE, and constructed by the Pine Island Construction Co., the bridge will be described in the book "Beautiful Michigan" by...

Man in a bright yellow safety vest and a green cap, standing on the far left of the group.

Man in a dark jacket and a dark cap, standing in the second row from the left.

Man in a dark suit and glasses, standing in the second row from the left.

Man in a dark jacket, standing in the second row from the left.

Man in a dark jacket, standing in the second row from the left.

Man in a bright yellow safety vest, kneeling in the front row.

Man in a white shirt and a yellow safety vest, kneeling in the front row.

Man in a dark jacket, standing in the second row from the right.

Man in a dark sweater with a pattern, standing in the second row from the right.



Man in a dark jacket and glasses, standing in the second row from the right.

Man in a light-colored shirt and a yellow safety vest, standing in the second row from the right.

Lawrence Technological University Beam Testing

- 3 salvaged beams tested
- Last one broke on October 31st, 2104

Field Specimens from Kent County - Decommissioned Box Beams



Methods: Ultrasonic Assessment,
Electro-chemical, MFL, In-situ
Hardness & Flexural Residual
Capacity

Overview of Plainfield Bridge #6, Childsdale Avenue




Objectives

- Evaluate the residual flexural strength of 3 side-by-side box beams decommissioned after 35 years of service due to deterioration.
- Assess the observed deterioration in both concrete quality and prestressed strands and relate to flexural capacity of beams.

Nondestructive Testing Methods

- ultrasonic assessment for delamination and void detection
- electro-chemical half-cell assessment for detecting corrosive environment
- impact hammer assessment of surfaces to detect variations and potential delamination
- magnetic flux leakage to determine loss of cross sectional area of rebar and strands.

Salvaged Beam Configuration




Each beam was 43'-8" long, 36" wide and 21" deep.

Selected beams:

- 2 exterior beam,
- 1 interior beams

Typical Cross-section

Evaluation of area **without** significant signs of corrosion




Scanning Strand
#4



Scanning on Less
Corroded Strand

Evaluation of area **with** significant signs of corrosion




Scanning Strands 9 & 10




Scanning on Corroded Strands

Comparison – Salvaged Beam #1



Scanning at 100 kHz



Scanning at 100 kHz

Electro-chemical Half-cell Assessment of Salvaged Beams



Half-cell potential measurement of bottom strands

6"x6" grids mapped at the bottom of the box beams.


Readings taken from the intersection of these grids.

ASTM C876 Half cell potential(mv)


Chance of corrosion

- < -500 – Visible corrosion
- -350 to -500 – 95%
- -200 to -350 – 50%
- > -200 – 5%



Half-Cell Potential Maps from Salvaged Beam #3 Test 2




Half-Cell Potential Maps from Salvaged Beam #2 Test 2




Magnetic Flux Leakage




Scan of Southern Half of Kent County Salvage Beam H6, Strand 6




Half-Cell Potential Maps from Salvaged Beam #1 Test 1, 2 & 3



Graphical Representation S3-North End, Run #10, Salvaged Beam #1.



Flexural Testing of Salvaged Beams



Loading Set-up for Salvaged Beam

Failed Beams




Salvaged Beam #3 (A1)



Salvaged Beam #1 (J11)


Experimental Results of Residual Flexural Testing of Salvaged Beam, J11

Load vs. Displacement



Experimental Results of Residual Flexural Testing of Salvaged Beams: J11, H6 & A1

Combined Graph of Load against Displacement



Beams	Cal. Ultimate Load (lb)	Assumed Cross-sectional Area Loss
Beam #1 (J11)	29500	20% , 8 Strands Actively Engaged
Beam #2 (H6)	39096	20% , 10 Strands Actively Engaged
Beam #3 (A1)	42011	15% , 10 Strands Actively Engaged
	-----	-----
	Load (lb)	(inches)
Beam #1 (J11)	31200	6
Beam #2 (H6)	36970	9
Beam #3 (A1)	40160	7.5

Where do we go from here?

- Testing has been completed on 3 beams
- There is a correlation deterioration and the strength of the beam with the testing that has been done
- Additional beams should be tested to increase the sample size and verify the results so far.
- Develop a methodology to correlate the data collected to a load rating.

- Questions